



Preliminary Information

PIP5775B MIL/Service Engine Soon Light Illuminated with DTC P11D5 set

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 2500HD/3500HD	2021	All	All	L5P	All
GMC	Sierra 2500HD/3500HD	2021	All	All	L5P	All

Involved Region or Country	North America
Condition	Some customers may comment on the MIL/Service Engine Soon light being illuminated and the technician may find DTCs P11D5 set.
Cause	Software anomaly

Correction:

Caution: This Document Only Applies To VINs NOT Covered by Service Update N212331790 Please Verify In VIS Before Proceeding

If campaign N212331790 does NOT apply to this vehicle and there are no obvious exhaust or NOx sensor issues, update the ECM with the latest software available in TIS2Web and release the vehicle.

Programming notes:

- After programming turn the vehicle off
- Start vehicle.
- Shut off vehicle
- Turn ignition on, engine off
- Clear codes.

Version History

Version	3
Modified	01/21/2021 - Created. 02/15/2021 - Updated to change the correction. 04/21/2021 - Updated to remove P20EE and add N212331790

